

21 | 13 | 9 | HEAD / JAMB INT. DOOR | 5



22 | 18 | DOOR THRESHOLD | 14



10 | MTL. DOOR JAMB | 6



OPENING FLASHING | 2



15 | 11 | MTL. DOOR HD. | 7



WINDOW HEAD/JAMB | 3



SCREED | 20 | 16 | WINDOW JAMB POST | 12





DOOR THRESHOLD | 8



WINDOW SILL TRIM | 4

CADFILE:
PLOT DATE:

COPYRIGHT ©

No.	Date	Issue / Description
	11.07.2002	OWNER REVIEW

IT IS THE CLIENTS RESPONSIBILITY PRIOR TO OR DURING CONSTRUCTION TO NOTIFY THE ARCHITECT IN WRITING OF ANY PERCEIVED ERRORS OR OMISSIONS IN THE PLANS AND SPECIFICATIONS OF WHICH A CONTRACTOR SHOULD REASONABLY BE AWARE. THE BUILDING CODES AND METHODS OF CONSTRUCTION CHANGE FREQUENTLY BY APPLY. WRITTEN INSTRUCTION PROVIDED BY SUCH AGENCIES SHALL BE FOLLOWED. IF THESE PROCEDURES ARE NOT FOLLOWED, THE CLIENT OR CLIENTS SUBCONTRACTORS PROCEEDING WITH THE WORK, THE CLIENT WILL BE RESPONSIBLE FOR ANY DEFECTS IN CONSTRUCTION IF THESE PROCEDURES ARE NOT FOLLOWED.

Consultant:

Project:

UCI - EAST CAMPUS STUDENT APTS. PHASE 1
IRVINE
CALIFORNIA

2001077

KTGY GROUP, INC.
Architecture Planning
17992 MITCHELL SOUTH
IRVINE, CA 92614
(949) 851-2133
(949) 851-5156 FAX

License Stamp:

CONTRACT SET

Principal in Charge:	D. McALLISTER
Project Director:	D. McALLISTER
Project Manager:	W. WONG
Project Designer:	D. TAITANO
Checked By:	

Sheet Title:
DETAILS

Sheet No.:
D-3