

SCALE: 1/8"=1'-0"

Δ	CCD 04 (Rf 0287)	12-17-08
Δ	CCD 04 (Rf 0289)	12-17-08
Δ	CCD 04	12-17-08
Δ	CCD 011	04-10-09

- ① 4" W. DOWN.
- ② 2" W. DOWN.
- ③ 2" V. DOWN.
- ④ 4" W. UP.
- ⑤ 2" W. UP.
- ⑥ 2" V. UP.
- ⑦ 4" W. STUD OUT ABOVE CEILING AND CAP FOR FUTURE CONNECTIONS.
- ⑧ 2" V. STUD OUT ABOVE CEILING AND CAP FOR FUTURE CONNECTIONS.
- ⑨ 1/2" LLOW IN WALL TO P10. MOUNT P10 18" ABOVE FINISHED FLOOR AT BACK OF CASEWORK. WATER CONNECTION TO COFFEE MAKER [129].
- ⑩ LLOW, L1HW AND L1HWC RISERS.
- ⑪ L1LOW, L1HW AND L1HWC RISERS. SEE M9.03.
- ⑫ 2" W. IN WALL.
- ⑬ 2" W. UP TO P7A.
- ⑭ 4" W. AND 2" V. IN WALL.
- ⑮ 1/2" LLOW AND 1" COPPER DRAIN IN WALL TO P11. MOUNT P11 18" ABOVE FINISHED FLOOR AT BACK OF CASEWORK. PROVIDE CONNECTIONS TO ICE MACHINE [127]. SEE DETAIL 7 ON M10.05.