## SECTION 05 90 99

## HISTORIC STAIR RESTORATION

## PART 1 - GENERAL

#### 1.01 DESCRIPTION

- A. This Section describes the requirements for the restoration of existing historic stairs, including but not limited to the following:
  - 1. Historic Stairs 1, 2, 3, and 4:
    - a. Maintain and repair as required plywood protection for stone treads installed during the soft demolition phase.
    - b. Repair damaged stair treads and landings as required with polyester resin.
    - c. Re-surface stone stair treads and landings with 300-400 grit and seal with a water and oil repellent sealer.
    - d. Repair and refurbish wood handrails and steel supports.
  - 2. Historic Stairs 5, 6, 7, 8 and 9:
    - a. Maintain and repair as required plywood protection installed during the soft demolition phase.
    - b. Re-surface stone treads and landings utilizing a 300-400 grit and seal with a water and oil repellent sealer.
    - c. Repair stone stair treads and landings as required with polyester resin. Repair includes holes drilled thru stone, and repair of chips and cracks as required.
    - d. Repair and refurbish wood handrails and supports.
- B. Related Sections:
  - 1. Restoration of decorative plaster ceilings and walls surfaces is specified in Section 09 20 99.
  - 2. Restoration of marble, terrazzo and tile flooring is specified in Section 09 30 99.
  - 3. Restoration of marble wall panels, base, wainscots and trim pieces is specified in Section 09 75 99.
  - 4. Architectural woodwork restoration in Section 06 40 29.
  - 5. Volume II, Section C, Historic Guidelines & Criteria.

#### 1.02 SUBMITTALS

- A. Product Data: Include information on materials and installation instructions.
- B. Mock-up: Construct a mock-up of a refurbished stair tread and railings where directed by the County's Representative. Mock-up shall incorporate materials and procedures to be incorporated in the work. Make modifications as directed until the mock-up is approved. Approved mock-up shall serve as a standard of quality of historic stair restoration.

## 1.03 QUALITY ASSURANCE

A. The work of this Section shall be performed by personnel with a minimum of 3-years experience in the restoration of stone surfaces similar to those required for this Project with not less than two installations of comparable size and complexity.

# PART 2 - PRODUCTS

- 2.01 MATERIALS
  - A. General: Provide materials as required for refurbishing existing stone stair surfaces.
  - B. Sealer: Mira Seal or approved equal water and oil repellent sealer recommended for use on stone of the type required.
  - C. Polyester Repair Resin: Akemi Marble Repair Compound or approved equal.

# PART 3 - EXECUTION

- 3.01 INSTALLATION
  - A. Refurbish historic stair treads and landings to the satisfaction of the County's Representative.

# END OF SECTION